

POUGHKEEPSIE
Department 539
South Road Laboratory

May 22, 1959

MEMO TO: Mr. J. D. Calvert
SUBJECT: No Operation CONTROL Instruction

A review of the usefulness of the No Operation CONTROL instruction, code 0000 0000, has revealed that there seems to be no justification for the instruction at this time. This memo confirms our agreement to eliminate the No Operation control function.

In the future, a CONTROL instruction with code 0000 0000 will cause the Exchange Program Check indication on all input-output units.

A. Padegs

A. Padegs
Associate Engineer
7030 Engineering Planning

AP/pkb

cc: Mr. J. K. Crawford
Mr. H. E. Childs
Mr. R. A. Skov
7030 Product Planning
7030 Engineering Planning
T. G. Floros

H. D. Kolobay