



MCH LANITIS

LOC BORE

OPD GRD RIM FACE, REFERENCE SD

MCH LANDIS

LOC BORE

OPD GRD RIM FACE, OPP SIDE

MCH LANDIS

LOC BORE RIM FACE REF SIDE

OPD FIN GRD TEETH

MCH REISHAUER

LOC NOT SIGN.

OPD. WASH

MACH. SLUSH TANK

OPD CU PLATE

OPD CARBURIZE

OPD STRIP CU

OPD HON QSDRAW HARDEN, QUENCH & DRAW

OPD SAND BLAST

INSPECT ALL GRS

LOC GR OD PITCH PINS REF SIDE

~~INSPECT ALL GRACE REF SIDE~~

GRD BR ONLY

MCH BRYANT

LOC GR ODS PITCH PINS OPP SIDE

OPD GRD BRSHUB FC REF SIDE

MACH. BRYANT ~~FC REF SIDE~~

LOC GRD & PITCH PINS REF SIDE

OPD GRD HUB FC

MACH BRYANT

LOC BORE

OPD GRD OD

MCH NORTON

LOC BR&RIM FC SH HUB SIDE

OPD GRD RIM FACE LNG HUB SD

MCH NORTON

LOCATE ON BORE

OPD GRD RIM SH HUB SIDE

MCH LANDIS

LOC BORE

OPD FIN GRD TEETH

MCH REISHAUER

OPD CK BN NI ET

MCH BENCH

LOC NOT SIGN

OPD STRESS REL

MCH LANDIS

LOC BORE

OPD FIN GRD TEETH

MCH REISHAUER

OPD CK BN NI ET

MCH BENCH

LOC NOT SIGN

OPD STRESS REL

MCH FURNACE

LOC GR DD S FIX

BROACH

OPD RRH KEYWAY

MCHLAPINTE HORIZONTAL BROACH

LOC AR TE

OPD BRUSH SIDES

MCH OSBORNE

LOC HAND OPER

OPD BRUSH TOPS

MCH HAMMOND

LOC HAND OPER

OPD DEBURR COMP

MCH BENCH

LOC HAND OPER

OPD WASH

MCH SLUSH TANK

LOC HAND OPER

OPDET CH

MCH VIBRA PEEN